

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well well
2. NAME OF OPERATOR
SUNDANCE OIL COMPANY
3. ADDRESS OF OPERATOR
Suite 510, 1776 Lincoln St., Denver, CO 80203
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FSL, 1980' FEL, Unit J
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>		<input type="checkbox"/>
(other) SET SURFACE CASING	<input type="checkbox"/>		<input type="checkbox"/>

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 12 1/4" surface hole at 10:45 a.m. 7/12/79. Drilled to 1775'. Ran 45 jts. of 8 5/8", 24#, Range 3 surface casing to 1775'. Cemented with 250 sx 3% Econolite + 250 sx Class C, 2% CaCl₂. Plug down at 10:15 a.m. 7/14/79. Circulated 50 sx. Pressured to 800#. ²WOC.

5. LEASE
NM-15019
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Cone Federal
9. WELL NO.
15
10. FIELD OR WILDCAT NAME
Tomahawk, San Andres
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
NW SE Section 31, T.7S., R.32E.
12. COUNTY OR PARISH
Roosevelt
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
4462' GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

RECEIVED

JUL 19 1979

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO


Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Richard O. Dimit TITLE V-P, Production DATE July 17, 1979

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:



201 10 11
10 11 10

10 11 10 11 10

RECEIVED
JUL 24 1973
O.C.D. HOBBS, OFFICE