

**UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY**

SUBMIT IN TRI
(Other instruction
verse side)

ATE*
n re

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 12852

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Holly Federal 27 Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Wildcat

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec 27 T-7S R-37E

12. COUNTY OR PARISH

Roosevelt

13. STATE

NM

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Holly Energy Inc.

3. ADDRESS OF OPERATOR

P.O. Box 726 Artesia, New Mexico 88210

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

1980 ~~ELS~~ 1980 FEL Sec 27 T-7S R-37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

4046.8 Gr

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

Set intermediate casing

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drill 11" hole to 3757'. Run 85 joints 8 5/8(1918' 32# & 1833 24#) and set @ 3751'. Cement with 1000 sacks pacesetters C lite with 18% salt, 1/4# celo seal and 200 sacks Class C 2% calcium. Did not circulate cement, after waiting 6 hrs. ran temperature survey, found top of cement 350' from surface (30' cement inside 13 3/8 surface casing). After waiting 18 hrs. tested casing and B.O.P. to 1000 #PSI, held 30 min, O.K. Drill out with 7 7/8 bit. (8-16-80)

RECEIVED

SEP 12 1980

U. S. GEOLOGICAL SURVEY
ROOSEVELT, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

Robert Lloyd

TITLE Superintendent

DATE 9-4-80

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DATE

SEP 18 1980

U.S. GEOLOGICAL SURVEY
ROOSEVELT, NEW MEXICO

*See Instructions on Reverse Side