| Form 9-331 N <sup>11</sup> , OIL CONS. COMMISSION<br>Dec. 1973 P. J. BOX 1980   | Form Approved.<br>Budget Bureau No. 42–R1424   |  |
|---|--|--|
| Dec. 1973 P. J. BOX 1980<br>UNITEDS STATESMEXICO 88240  | 5. LEASE   |  |
| DEPARTMENT OF THE INTERIOR  | NM 54437   |  |
| GEOLOGICAL SURVEY   | 6. IF INDIAN, ALLOTTEE OR TRIBE NAME   |  |
|   |  |  |
| SUNDRY NOTICES AND REPORTS ON WELLS   | 7. UNIT AGREEMENT NAME   |  |
| (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form $9-331-C$ for such proposals.)  | 8. FARM OR LEASE NAME  |  |
| 1. oil gas  | <u>Conquest</u> Federal  |  |
| well and well other   | 9. WELL NO.  |  |
| 2. NAME OF OPERATOR   | 1  |  |
| Morris R. Antweil   | 10. FIELD OR WILDCAT NAME  |  |
| 3. ADDRESS OF OPERATOR  | Vada Penn  |  |
| P. O. Box 2010, Hobbs, NM 88241   | 11. SEC., T., R., M., OR BLK. AND SURVEY OR  |  |
| 4. LCCATION OF WELL (REPORT LOCATION CLEARLY. See space 17  | AREA<br>Sec. 25 T8S-R35E   |  |
| below.)<br>AT SURFACE: 660' FSL &660' FEL of Sec. 25  | 12. COUNTY OR PARISH 13. STATE   |  |
| AT TOP PROD. INTERVAL:  | Roosevelt NM   |  |
| AT TOTAL DEPTH:   | 14. API NO.  |  |
| 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,   |  |  |
| REFORT, OR OTHER DATA   | 15. ELEVATIONS (SHOW DF, KDB, AND WD)  |  |
| REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:  | 4141' GR   |  |
| TEST WATER SHUT-OFF   |  |  |
| FRACTURE TREAT  |  |  |
| SHOOT OR ACIDIZE  |  |  |
| REPAIR WELL   | (NOTE: Report results of multiple completion or zone change on Form 9-333.)  |  |
|   | change on Form 9-330.)   |  |
| CHANGE ZONES  |  |  |
| ABANDON*  |  |  |
| (other) intermediate casing, cement, a test   |  |  |
| 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statistic) including estimated date of starting any proposed work. If well is comeasured and true vertical depths for all markers and zones pertine Drilled 11" hole to 3200'. Ran 79 jts. 8 5/8 cemented at 3200' with 650 sx Halliburton lig 1/4#/sk flocele and 2% CaCl and 300 sx Class Plug down 2:00 PM 9/19/85. Did not circulate survey after 6 hours. WOC 15 hours. Tested Drilled out with 7 7/8" bit. | <pre>directionally drilled, give subsurface locations and<br/>nt to this work.)*<br/>" 24 and 32# J-55 casing and<br/>ht cement containing 18% salt,<br/>"C" containing 2% CaCl<sub>2</sub>.<br/>cement. TOC 500' by temperature</pre> |  |
|   |  |  |
|   |  |  |
|   |  |  |
|   |  |  |
|   |  |  |

| Subsurface Safety Valve: Manu. and Type                                      | Set @   | Ft. |
|--|---------|-----|
| 18. Thereby certify that the foregoing is true and correct                   |         |     |
| SIGNED   | 9/23/85 |     |
| ACCEPTED FOR RECORD (This state tor Federal or State office use) APPROVED BY |         |     |
| APPROVED BY PETER TO DATE DATE DATE  |         |     |
| OCT 3 1985   |         |     |
| BUREAU OF LAND MANAGEMENT<br>ROSWELL RESOURCE AREA                           |         |     |