STATE OF NEW MEXICO

SINIE OF NEW MEXICO		
ENERGY AND MINERALS DEPAR	RTMEN	T
NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		•
FILE		
U.S.G.S		•
LAND OFFICE		•
OPERATOR	П	•

Form C-103

NO. OF COPIES RECEI	VED	OIL CONSERVAT		Revised 10-1-78		
DISTRIBUTION		P.O. Bo	ox 2088			
SANTA FE		SANTA FE, NEW	MEXICO 87501	5a. Indicate	Type of Lease	
FILE				State X	Fee	
U.S.G.S						
LAND OFFICE				5. State OII	& Gas Lease No.	
OPERATOR						
	CHADDY NOT	LOCC AND DEDOOTE ON HELL			3640	
AND NOT HER THE FOR		ICES AND REPORTS ON WELL		ł	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
			EN OR PLUG BACK TO A DIFFERENT	i	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
		ATTON FOR PERMIT-" (FORM	(C-101) FOR SUCH PROPOSALS.)		XXXXXXXXXXXXXXXXXX	
1. OIL	GAS WELL	T ATUER		7. Unit Agree	ment Name	
	WELL _	OTHER		<u> </u>	-	
2. Name of Operator				8. Farm or Lease Name		
	Read & Stevens, Inc.		DAVID STATE			
3. Address of Operato				9. Well No.		
P.0. Box 1518, Ros	SWOII, NM	88201		1		
4. Location of Well				10. Fleld and	Pool, or Wildcat	
UNIT LETTER P	. 660	FEET FROM THE East	LINE AND 660 FEET FROM	Wildca		
			ETHE MAD GOO LEET THOM	XXXXXXXXXXXXXX	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
THE South LINE	E. SECTION_	32 TOWNSHIP 7S	RANGE 35E NMPM		XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	XXXXXXXXXX	5. Elevation(Show wheth	er DF,RT,GR,etc.)	12. County	XXXXXXXXXXXXXXXX	
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	XXXXXXXXXX	4237	.1' GL	Roosevelt	XXXXXXXXXXXXXXXXXX	
	Check Appr	opriate Box To Indicate	Nature of Notice, Report or Oth	ver Data		
NOTIC	CE OF INTENT	ION TO:	SUBSEQUENT RE	PORT OF:		
						
PERFORM REMEDIAL N	├	PLUG AND ABANDON	REMEDIAL WORK		NG CASING	
TEMPORARILY ABANDO		CHANGE PLANS	COMMENCE DRILLING OPNS.	PLUG A	ND ABANDONMENT	
PULL OR ALTER CASI	ING L		CASING TEST AND CEMENT JOB			
OTHER			OTHER PERFORATE & A	CIDIZE	X	
Describe Proposed or	Completed O	norations/Classia state	1. all pertinent details, and give	nostinost dat	an Including and I	
		sed work) SEE RULE 1103.		perrinent dar	es, including esti-	
4-9-85	RU. Trip o	ut w/rods, pump, & tbg.	Perf 4511'-4599', 36 holes, tr	trip in w/pkr & RBP, left		
	€ 4500', SI	DON.				
4-11-85	4-11-85 RU Bell wireline, ran collar locater, checked perfs, OK, correlated BP, set BP, tested €					
		·	, acid w/3000gals 15% MCA acid		•	
			max rate 4 BPM, avq rate 3.6 BP	-	•	
	900psi, 10	min 800psi, 15min 600psi	, balled out, surged off, load	71.4 BA, 25 BB	Ls flush,	
	total 96.4	BBLs, swbd 38 BBLs, FL	@ 2700', tr of oil.			
4 17 05	C) A CCCA.	TD 7401 - 1 1 00 551		6 BBI -	- A 1 -	
4-13-85 FL @ 2800'. TP 340psi, swbd 22 BBLs, total load rec'd 110 BBLs, 12 BBLs over load, sk of oil <u>+</u> 1%. Acidize w/6000gals 20% NE-Fe acid w/ballsealers, max press 3300psi, avg					•	
			rate 6.5 BPM, ISIP 1400ps1, 5m	in ibuupsi, iu	nin	
	1200051, 1	י אונות כסו ,ופקטטוו וווות	swbd & flwd 55 BBLs, 108 BLTR.			
I hereby certify tha	it the Infor	mation above is true and	complete to the best of my kno	wledge and bel	lef.	
\mathcal{A}	A	~P.	·	-		
SIGNED CO	-Xv	TITLE	E Drilling and Production Mana	ig e r DATE	4-15-85	
		· · · · · · · · · · · · · · · · · · ·				
CHEE		BY JERRY SEXTON		Λ	PR 2 3 1985	
APPROVED BY	DISTRICT	SUPERVISOR TITLE	F	DATE A	IFK Z O IJOJ	

RECEIVED
APR 19 1985

HOBBS CARRES