

UNITED STATES N. M. ON CONS. COMMISSION
DEPARTMENT OF THE INTERIOR BOX 1980
BUREAU OF LAND MANAGEMENT HOBBS, NEW MEXICO 88240

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-0321281

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Todd Lower S/A Unit

8. FARM OR LEASE NAME

Todd Lower S/A Ut. Sec. 29

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

Todd Lower S/A Assoc.

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 29, T7S, R36E

12. COUNTY OR PARISH

Roosevelt

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

MURPHY OPERATING CORPORATION

3. ADDRESS OF OPERATOR

P. O. Drawer 2648, Roswell, NM 88202-2648

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)
At surface

1980' FSL & 1980' FWL, Section 29, T7S, R36E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4141' GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) cement production casing

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

August 1, 1988 - TD 4400'. Ran 4409' (103 joints) 5-1/2" 15.5# J-55 ST&C casing and set at 4400'. Cement with 500 gals. mud flush. Lead: 600 sacks Howcolite, 5#/sack Gilsonite & 1/4#/sack Flocele. Tail: 200 sacks Class H, 5#/sack salt. Circulated 40 sacks cement to pit. Plug down at 4:00 a.m. MST August 1, 1988.

18. I hereby certify that the foregoing is true and correct

SIGNED

Melinda K. Hickman
Melinda K. Hickman

TITLE Production Supervisor

DATE August 15, 1988

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD
PETER W. CHESTER

DATE

AUG 23 1988

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side