

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
HOBBS, NEW MEXICO 88240

Expires August 31, 1985  
5. LEASE DESIGNATION AND SERIAL

NM 69680

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "28" A Com

9. WELL NO.

10. FIELD AND POOL OR WILDCAT  
North Bluitt  
(Siluro Devonian)

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec 28, T-7-S, R-37-E

12. COUNTY OR PARISH 13. STATE

Roosevelt

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

H. L. Brown, Jr.

3. ADDRESS OF OPERATOR

Post Office Box 2237, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

660' FNL & 660' FEL of Section 28, T-7-S, R-37-E, Unit A

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4062.6 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

Sidetrack wellbore

(Note: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

1-06-91 Drilling at 8085'. Drillpipe parted with top of fish at 5314'.

1-11-91 Attempted to recover fish unsuccessfully for 5 days.  
Commenced Sidetrack around fish.

1-13-91 Drilling @ 5310' and hit fish w/ bit.

1-14-91 Again attempted to engage fish at 5310' unsuccessfully.  
Prep to Plug Back.

1-15-91 Pumped 700 sx Class "H" Cement @ 5661'. Top of Plug @ 5490'.  
WOC 24 hrs.

1-16-91 Pumped 540 sx Class "H" Cement @ 5490'. Top of Plug @ 5295'.  
WOC 24 hrs.

1-17-91 Pumped 540 sx Class "H" Cement @ 5295', Top of Plug @ 5271'.  
WOC 24 hrs.

1-18-91 Commenced Sidetrack around fish. Bottom hole location unchanged  
and as permitted.

18. I hereby certify that the foregoing is true and correct

SIGNED

Mark A. Losch

TITLE

Production Engineer

DATE 3-8-91

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD  
PETER W. CHESTER  
DATE

MAR 11 1991

\*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT  
ROSWELL, NEW MEXICO