



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **MM-01171**
Unit **M**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	X
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 28, 19**55**

Well No. **1** is located **660** ft. from **N** line and **1960** ft. from **E** line of sec. **27**

C 24/4 SE/4 (1/4 Sec. and Sec. No.) **136** (Twp.) **30E** (Range) **187N** (Meridian)
Willcox (Field) **Chavez** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The subject well was plugged and abandoned October 27, 1955.

1. TD 2000' (Pawnee Sand)
2. Run electric logs to total depth.
3. Plugging Detail

Cement plug 2000'-2200' with 31 sacks
Cement plug 150' - 200' with 19 sacks
(8-5/8" casing @ 165')
Cement plug Surface - 15' with 5 sacks

POA

1-17-56

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **United States Smelting Refining and Mining Company**

Address **P. O. Box 1877**

Midland, Texas

By *George E. Anderson*
George E. Anderson
Title **Assistant to Manager**