

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TR  
(Other instructio  
verse side)DATE\*  
re-Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-10598

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Mark Federal

9. WELL NO.

1

10. FIELD AND HOLE, OR WILDCAT

J. Dearth & Sa  
Wildcat11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 30-T15S-R30E

12. COUNTY OR PARISH 13. STATE

Chaves

N. M.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

RECEIVED

JUL 17 1980

O. C. D.

ARTESIA OFFICE

1. OIL ☐ GAS ☐ OTHER ☒ Dry Hole

2. NAME OF OPERATOR

McClellan Oil Corporation

3. ADDRESS OF OPERATOR

P. O. Drawer 730, Roswell, New Mexico 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

1980 FSL &amp; 660 FEL

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3940 G.L.

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☒(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

4/18/80: Set cast iron bridge @ 3400' on wire line. Loaded hole and shot off 4½" casing @ 2900' F.G.L. Pulled 86 joints of 4½" casing. Ran tubing and spotted 10 sx. cement plug @ 3400'. Pulled tubing to 2950' and spotted 45 sx. cement plug. Cement filled to 2820'. Placed 10 sx. cement plug at surface. Heavy mud pumped between plugs. Set dry hole marker. Will restore surface to as near original condition as possible.

RECEIVED

MAY - 6 1980

U.S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

J. L. McClellan

TITLE Operator

DATE 5/2/80

(This space for Federal or State office use)

APPROVED BY (Orig. Sgd.) PETER W. CHESTER

TITLE ACTING DISTRICT ENGINEER

DATE JUL 13 1980

CONDITIONS OF APPROVAL, IF ANY: