



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office LC-060870
Lessor Union Oil Co. of Calif.
Unit OFFICE
APR 27 AM 10:21

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 2 is located 990 ft. from S line and 717 ft. from E line of sec. 4
15-3 (Twp.) 31-2 (Range) (Meridian)
Caprock-Lewis (Ext.) (Field) Chavez (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 4381 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We propose to drill to approximately 3165' to test the Sucias sand.
 Will cement surface casing at approximately 200' and circulate back to surface.
 Will cement pay string at total depth if pay encountered with approximately 200 sacks of cement.
 Will perforate and sandfrac.
 Rotary will be used to completion.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Bill A. Shelton

Address Box 1156
Lovington, New Mexico

By John M. Shelton
 Title Office Manager

