



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYLand Office LCLease No. 069832Unit 1

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		
Notice of Intention to Convert well to water injection		X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

December 31, 1962

Well No. 9-8 is located 1983 ft. from W line and 660 ft. from E line of sec. 5SE 1/4 Sec. 5  
(1/4 Sec. and Sec. No.)T-15-S  
(Twp.)R-31-E  
(Range)NMPM  
(Meridian)Caprock Queen  
(Field)Chaves  
(County or Subdivision)New Mexico  
(State or Territory)The elevation of the derrick floor above sea level is 4449 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Present Condition of WellTD 3161  
ETD 3161  
5 1/2" c 3139'  
Open hole 3139 - 3161  
Well shut in

RECEIVED

JAN 4 1963

O. C. C.  
ARTESIA, OFFICEProposed WorkClean out to TD of 3161  
Run plastic lined 2" tubing with tension packer  
Place well on water injection service.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Union Oil Company of CaliforniaAddress 205 East WashingtonLovington, New MexicoORIGINAL SIGNED BY  
RICHARD H. BUTLER  
UNIT ENGINEERBy Richard H. Butler  
Title Unit Engineer