

Form 9-331a
(Feb. 1951)


(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. 062-524a

Unit Federal-Saner

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY



SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

March 28, 1955

Well No. 3 is located 660 ft. from N line and 1980 ft. from W line of sec. 8

SE 1/4 SW 1/4 Sec. 8 15S 31E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

South Dickey Queen Chaves County New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

SINCLAIR OIL & GAS COMPANY - FEDERAL - SANER WELL NO. 3

9 5/8" csng	21#	New	350'	100 sx
7 " "	23#	New	3105'	200 sx

Contract to be made for a total depth of 3200' to test the Queen Sand 3105' to total depth. To be drilled with rotary tools.

John H. Reeves
J. T. Reeves

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SINCLAIR OIL & GAS COMPANY

Address 901 Fair Building

Port Worth 2, Texas

By J. T. Reeves

Title Division Superintendent
Production Department

Copy sent S. F.