



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Las Cruces
Lease No. 062-524 a
Unit Federal - Saner

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	<input checked="" type="checkbox"/>	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Fort Worth, Texas April 25, 19 55Well No. 4 is located 660 ft. from N line and 660 ft. from W line of sec. 8

<u>SW/4 SW/4 Sec. 8</u> (1/4 Sec. and Sec. No.)	<u>15 S 31 E</u> (Twp.) (Range)	<u>N 104 W</u> (Meridian)
<u>South Dickey Queen</u> (Field)	<u>Chaves</u> (County or Subdivision)	<u>New Mexico</u> (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

SINCLAIR OIL & GAS CO. - WELL NO. 4 - FEDERAL - SANER FARM

<u>9 5/8" casing</u>	<u>24 #</u>	<u>New</u>	<u>350'</u>	<u>100 sks</u>
<u>7 " casing</u>	<u>23 #</u>	<u>New</u>	<u>3105'</u>	<u>200 sks</u>

Contract to be made for a total depth of 3200' to test the Queen Sand 3085' to total depth. To be drilled with rotary tools.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Sinclair Oil & Gas Co.Address 901 Fair BuildingFort Worth 2, TexasBy J. T. ReevesTitle Division Supt- Production Dept.