



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. **LC-060830**Date **DEC 9 1955****1955 MAR 11 AM 11:29**

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	1
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 27, 19**55**

Federal-Headlin

Well No. **2-8** is located **1874** ft. from **[N]** line and **2086** ft. from **[E]** line of sec. _____
NE 1/4 of Section 8 **T-15-S** **R-11-E** **S.1. & 11.**
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
South Briscoe (area) **Chaves** **New Mexico**
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **Unknown at present** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

waited on cement 24 hours.

Tested casing with 1000 psi for 30 minutes. Okay.

Released pressure to drill 7-7/8" hole.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Union Oil Company of California**Address **619 West Ninth Street****Midland, Texas**

By

Title

Asst. Div. Engineer