

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Ambassador Oil Corporation		Address Box 326 Caprock, New Mexico				
Lease North Caprock Queen Unit # 2	Well No. 1-2	Unit Letter A	Section 1	Township 13 S	Range 31 E	
Date Work Performed 21 March 1959	Pool Caprock Queen		County Chaves			

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations ☐ Casing Test and Cement Job ☒ Other (Explain): **See Below**
☐ Plugging ☐ Remedial Work

Detailed account of work done, nature and quantity of materials used, and results obtained.

Loaded hole with oil, spotted 250 gal. mud acid on bottom, broke well down and flushed with 50 bbls. oil. Ran tubing rods and put on pump. IP 5 BOPD no water

Witnessed by <i>Curtis Miller</i>	Position <i>Project Supervisor</i>	Company <i>Ambassador Oil Corp.</i>
--------------------------------------	---------------------------------------	--

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA

D F Elev.	T D 3024	P B T D 3024	Producing Interval 3014 - 3014	Completion Date 3-21-59
Tubing Diameter 2"	Tubing Depth 3010'	Oil String Diameter 5 1/2"	Oil String Depth 3011'	
Perforated Interval(s)				
Open Hole Interval 3011' - 3024'		Producing Formation(s) Queen		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

Approved by <i>Donald R. Layton</i>
Title <i>Project Supervisor</i>
Date

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name <i>Donald R. Layton</i>
Position Donald R. Layton Project Supervisor
Company Ambassador Oil Corporation

