

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE  
(Other instructions  
reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-071392

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Pebble Queen Unit

8. FARM OR LEASE NAME

9. WELL NO.

10-8

10. FIELD AND POOL, OR WILDCAT

Caprock Queen

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

10-13-S, 31-E

12. COUNTY OR PARISH 13. STATE

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL WELL ☐ GAS WELL ☒ OTHER Dry (Never produced oil)

2. NAME OF OPERATOR

Great Western Drilling Company

3. ADDRESS OF OPERATOR

P. O. Box 1659, Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surfaceSE/4 of NE/4 Sec. 10, T-13-S, R-31-E  
330' from the East line & 2260' from North  
line of Sec.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4424 GR.

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐

PULL OR ALTER CASING

☐

FRACTURE TREAT

☐

MULTIPLE COMPLETE

☐

SHOOT OR ACIDIZE

☐

ABANDON\*

☐

REPAIR WELL

☐

CHANGE PLANS

☐

(Other)

☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐

REPAIRING WELL

☐

FRACTURE TREATMENT

☐

ALTERING CASING

☐

SHOOTING OR ACIDIZING

☐

ABANDONMENT\*

☒

(Other)

☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

Well 10-8 was loaded with 10# mud. A cement plug of 25 sacks was spotted @3020'. The 4 1/2" casing was pulled @1990'. A cement plug of 25 sacks was placed in the stub 4 1/2" @1990'. 25 sacks were placed in the surface pipe @300' and 10 sacks were placed at the surface. A proper marker will be placed and a cleanup made. (April 29-30, 1964)

18. I hereby certify that the foregoing is true and correct

SIGNED

*O.H. Crews*

O.H. Crews

TITLE

Adm. Coordinator

DATE

5/1/64

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

\*See Instructions on Reverse Side

APPROVED

JUL 15 1964

B. J. SMOOGER

DISTRICT MANAGER