

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

SEP 11 11 41 AM '68

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. <b>B-8631-3</b>	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name <b>Pebble Queen Sec. 11</b>
2. Name of Operator <b>GREAT WESTERN DRILLING COMPANY</b>		8. Farm or Lease Name
3. Address of Operator <b>P. O. Box 1659, Midland, Texas 79701</b>		9. Well No. <b>3</b>
4. Location of Well UNIT LETTER <b>C</b> , <b>2310</b> FEET FROM THE <b>W</b> LINE AND <b>330</b> FEET FROM THE <b>N</b> LINE, SECTION <b>11</b> TOWNSHIP <b>13-S</b> RANGE <b>31-E</b> NMPM.		10. Field and Pool, or Wildcat <b>Caprock Queen</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4417 GR</b>		12. County <b>Chaves</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**This hole was loaded with mud and a 75 sack cement plug spotted @ 3030'. 1150' of 5½" was pulled and 25 sack plug were spotted at 1150' and 312' with 10 sacks at the surface. A marker was placed. (7-20-68)**

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *O. H. Crews* **O. H. Crews** TITLE **Administrative Coordinator** DATE **August 29, 1968**

APPROVED BY *John W. Runyan* TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: