## NEW MEXICO OIL CONSERVATION COMMISSION (Refried 3-55)

MISCELLANEOUS REPORTS ON WELLS
(Submit to appropriate District Office as per Commission Rule 1108) 37

COMPANY AMBASSADOR OIL CORPORATION	3109 WINTHROP, FORT WORTH, TEXAS
NORTH CAPROCK QUEEN UNIT	ddress)
LEASE No. 2 TR. 20 WELL NO	UNIT S T R 31-E
DATE WORK PERFORMED 8-20-58	
	FOUL
This is a Report of: (Check appropriat	e block) Results of Test of Casing Shut-off
Beginning Drilling Operations	Remedial Work
	SET LINER, RECOMPLETED AS
Plugging	X Other INJECTION WELL.
Detailed account of work done, nature a	and quantity of materials used and results obtained.
RE-SET CALSEAL PLUG 3 TIMES BEFORE PLUG CASING SET AT 30341. CEMENTED WITH ICH	RAY NEUTRON AND CALIPER LOG. PLUGGED BACK LUG TO 3037. PLUG FAILED. CLEANED OUT AND HELD. RAN 89.5' 5½" OD 15.5# 8 RD. THD. (LINER) SXS. RAN TEMPERATURE SURVEY AND LOCATED UG AND CLEANED OUT TO T.D. PLACED WELL ON
Original Well Data:	TREFORIS OULI
DF Elev. 4043 TD 3054 PBD _	Prod. Int. 3040-54 Compl Date
Thng. Dia None Thng Depth None	Oil String Dia 7" Oil String Depth 3014
Perf Interval (s) None	
Open Hole Interval 3034-54 Prod	ucing Formation (s) QUEEN SAND
RESULTS OF WORKOVER:	BEFORE AFTER
Date of Test	PRODUCTION TEST - CONVERTED TO WATER INJECTION WELL
Oil Production, bbls. per day	· · · · · · · · · · · · · · · · · · ·
Gas Production, Mcf per day	
Water Production, bbls. per day	
• · ·	
Gas Oil Ratio, cu. ft. per bbl.  Gas Well Potential, Mcf per day	
<u>-</u>	
Witnessed by Don Layton	AMBASSADOR OIL CORPORATION (Company)
OIL CONSERVATION COMMISSION	I haraby contify that the information given
	my knowledge.
Name Mandelly Me	Name Soluted Orde
Title	Position CHIEF ENGINEER, SECONDARY RECOVERY DIV
Date	Commons AMBASSADOR OH CORPORATION