

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL	<input checked="" type="checkbox"/>	REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

March 13, 1957

(Date)

Dallas, Texas

(Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Landa Oil Company
(Company or Operator)

State D-10420
(Lease)

Hobbs Pipe & Supply Co.
(Contractor)

Well No. 1-F in the SE 1/4 NW 1/4 of Sec. 22

T. 13S, R. 31E, NMPM, Caprock-Queen Pool, Chaves County.

The Dates of this work were as follows: December 17, 1956

Notice of intention to do the work (was) ~~(was not)~~ submitted on Form C-102 on December 3, 1956
(Cross out incorrect words)

and approval of the proposed plan (was) ~~(was not)~~ obtained.

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

15 sx. cement at T. D. to 100 ft. above perforations; 2
25 sx. plug placed half out and half in of 5 1/2" casing
stub at 1800 feet and 5 sx. at surface

Witnessed by J. W. Mc Carthy
(Name)

Landa Oil Company
(Company)

Geologist
(Title)

Approved: OIL CONSERVATION COMMISSION

[Signature]
(Name)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name J. W. Mc Carthy

Position Geologist

Representing Landa Oil Company

Address 5738 N. Central Ex., Dallas, Texas

(Title)

(Date)