

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY Geror Oil Corporation, 1846 East Broadway, Tucson, Arizona
(Address)

LEASE State WELL NO. 6 UNIT N S 22 T 13S R 31E
DATE WORK PERFORMED 8-28-58 POOL Caprock Queen

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off
☐ Beginning Drilling Operations ☐ Remedial Work
☐ Plugging ☒ Other casing leak

Detailed account of work done, nature and quantity of materials used and results obtained.

5 1/2 inch casing was leaking at collar above braden head. Cause was due to "cross thread" condition. Replaced collar and three (3) feet of 5 1/2 inch casing.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. TD PBD Prod. Int. Compl Date
Tbng. Dia Tbng Depth Oil String Dia Oil String Depth
Perf Interval (s)
Open Hole Interval Producing Formation (s)


RESULTS OF WORKOVER:


| | BEFORE | AFTER |
|---------------------------------|-------------------|-------------------|
| Date of Test | <u> </u> | <u> </u> |
| Oil Production, bbls. per day | <u> </u> | <u> </u> |
| Gas Production, Mcf per day | <u> </u> | <u> </u> |
| Water Production, bbls. per day | <u> </u> | <u> </u> |
| Gas-Oil Ratio, cu. ft. per bbl. | <u> </u> | <u> </u> |
| Gas Well Potential, Mcf per day | <u> </u> | <u> </u> |
| Witnessed by <u> </u> | | |

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name 
Title
Date

Name 
Position President
Company Geror Oil Corporation