

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

MISCELLANEOUS REPORTS ON WELLS

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Report by Checking Below

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	X	REPORT ON REPAIRING WELL	
REPORT ON RESULT OF PLUGGING WELL		REPORT ON RECOMPLETION OPERATION		REPORT ON (Other)	

May 18, 1955 Midland, Texas
(Date) (Place)

Following is a report on the work done and the results obtained under the heading noted above at the

Salsich, McGrath & Smith Amerada-State
(Company or Operator) (Lease)

Jennings Drilling Company Well No. 1 in the NW 1/4 NW 1/4 of Sec. 19
(Contractor)

T. 13-8, R. 32-E, NMPM, Caprock Pool, Lea County.

The Dates of this work were as follows: May 1955

Notice of intention to do the work (was) (YES) submitted on Form C-102 on May 17, 1955, (Cross out incorrect words)
and approval of the proposed plan (was) (was not) obtained. (Verbal permission of Mr. Porter of New Mexico Oil Conservation Commission)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

8-5/8 inch surface casing set at 305. Tested with 1000# pressure 30 minutes.
No drop in pressure.

Witnessed by Neil E. Salsich Salsich, McGrath & Smith Partner
(Name) (Company) (Title)

Operator says cement circulated
Approved: OIL CONSERVATION COMMISSION

(Name)

(Title) (Date)

I hereby certify that the information given above is true and complete to the best of my knowledge.

Name: R. Searle McGrath

Position: Partner

Representing: Salsich, McGrath & Smith

Address: 302 Petroleum Life Building, Midland, Texas