

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **New Mexico**
Lease No. **03927**
Unit **Government**
Cities Service Oil Co.

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

January 12, 1955

Well No. **1** is located **660** ft. from **N** line and **1900** ft. from **E** line of sec. **34**
38 38 34 **13-3** **31-3** **N-12-R**
 (1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Dickey-Allen (Ext.) **Chaves** **New Mexico**
 (Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **4430** ft. (Est.)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)


This well was drilled to 3033' in anhydrite. Ran 92.7 joints (3027') of 14" 55 J-5553 casing set at 3033' and cemented with 300 sacks of neat cement. Plug was down at 5:30 P.M. January 9, 1955. Cement was allowed to set 48 hours before testing for shut-off. Bailing test to determine shut-off was satisfactory. Drilling resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Cities Service Oil Company**

Address **Box 97**

Hobbs, New Mexico

By 

Title **Asst. Dir. Dept.**