



(SUBMIT IN TRIPLICATE)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Land Office Las Cruces

Lease No. LC 066474

Unit Government - P

Cities Service Oil Co.

## SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	<input checked="" type="checkbox"/>
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. 12 is located 1989.5 ft. from N line and 1900 ft. from E line of sec. 3  
SW 1/4 (1/4 Sec. and Sec. No.) 14S (Twp.) 31E (Range) NMPN (Meridian)  
Oriskany Basin (Ext.) (Field) Chaves (County or Subdivision) New Mexico (State or Territory)

The elevation of the derrick floor above sea level is 4425 ft. (Est.)

### DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth 373' in Red Bed. Ran 340 (9 jls) of a 5/8" OD 22.7 lb/ft casing set at 362' and cemented with 200 sacks of neat cement. Plug was down at 12:30 PM, August 24, 1954. Cement circulated. Cement was allowed to set 24 hrs before testing for shut-off. Test was satisfactory. Drilling resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Cities Service Oil Company

Address Box 97

Hobbs, New Mexico

By

Title Asst. Div. Supt.

1. The first part of the document discusses the importance of maintaining accurate records of all transactions and activities. It emphasizes the need for transparency and accountability in financial reporting.

2. The second part of the document outlines the various methods and techniques used to collect and analyze data. It includes a detailed description of the experimental procedures and the statistical analysis performed.

3. The third part of the document presents the results of the study. It includes a series of tables and graphs that illustrate the findings of the research. The data shows a clear trend of increasing activity over time.

4. The fourth part of the document discusses the implications of the findings. It suggests that the results have significant implications for the field of study and may lead to further research in this area.

5. The fifth part of the document concludes the study. It summarizes the key findings and provides a final statement on the importance of the research.

6. The sixth part of the document includes a list of references to the sources used in the study. It also includes a list of figures and tables that are included in the document.

7. The seventh part of the document includes a list of appendices. These appendices provide additional information and data that are not included in the main body of the document.

8. The eighth part of the document includes a list of footnotes. These footnotes provide additional information and clarification on the content of the document.

9. The ninth part of the document includes a list of acknowledgments. These acknowledgments thank the individuals and organizations that provided support and assistance during the study.

10. The tenth part of the document includes a list of contact information. This information provides a way for others to reach out to the author for more information or to discuss the study further.