

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. AM 080122

Unit 2A-PODSU Tract 3

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	<u>Workover</u> X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 17, 1964, 19__

Well No. 3-2A is located 330 ft. from S line and 990 ft. from E line of sec. 8

SW/4 SW/4 Section 8 T18S R31E _____
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Caprock Queen Chaves New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4052' ft. (GL)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Tested well for response to water flood. (Well originally temporarily abandoned)
Flowed 24 hours; 2 barrels oil, FTP 300#.

Killed well. Ran 2-3/8" tubing set at 2660'. Opened well on 3/4" choke, flowed
24 hours, 1 barrel oil, no water, gas TSTP, FTP 90#.

Well restored to oil production status.

RECEIVED

JUN 19 1964

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

ARTESIA, OFFICE

Company Phillips Petroleum Company

Address Box 2130

Hobbs, New Mexico

By W. C. [Signature]

Title Office Manager