



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office

Lease No. I.C-062486

Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

~~Notice of conversion to Input~~
(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Federal Trigg May 5 1961

Well No. 10-0 is located 1980 ft. from XXX line and 1980 ft. from E line of sec. 9

SE/4 9 14-S # 31-E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

Caprock Queen Chaves New Mexico
(Field) (County or Subdivision) (State Territory)

The elevation of the derrick floor above sea level is 4160 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Tubing and sucker rods were pulled April 13, 1961 and well was cleaned out to Total Depth of 2796'. We ran 2496' of 2-3/8" EUE 4.7# J-55 Smls. Cement Lined tubing with Haliburton R-3 packer landed at 2498'. Packer was pressure tested for leakage. Began injection of 200 bpd on April 15, 1961, but injection pressure has climbed and rate is considerably lower at the present time. Formation will have to be treated at a later date.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company John H. Trigg Company

Address Post Office Box 106

Valjamar, New Mexico

By [Signature]

Title Production Clerk