## (SUBMIT IN TRIPLICATE)

## UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Budget	Bureau	No.	42-R358.4
Form A	pproved		

Las Gruces

Land Office

LC-962486

OSUNDRY	NOTICES	AND	<b>REPORTS</b>	ON	WELLS

	<u></u>
NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING.
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT (Temp)
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL.	Report in change of status X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

		February 19		
Well No. is loca	located ft. from	<b></b>	ft. from W	line of sec.
mit mit of sec. 9	14-8	31-E MIPH		
(¼ Sec. and Sec. No.)  Caprock Queen	(Twp.)	Range) (Meri	dian) <b>New Ne</b> n	rice
(Field)	(County or	Subdivision)	(State or	Territory)

The elevation of the derrick floor above sea level is ft.

kb= 4126

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Rig up well service unit on November 14, 1962 and pull rods and tubing out of hole. Pumping unit was moved on November 12, 1962.

This well's production had declined well below the enunumic limit and the equipment was needed in another location. We propose to leave this well shut-in until it becomes eligible for conversion to water injection.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company	John H, Trigg Company		
Address	No t Office Bex 106		7
	Maljamar, New Mexico	Ву	Sien Site
		Title	Production Clerk