



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Las Cruces
Lease No. 10 68474
Unit Government
Cities service oil

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 6, 1954

Well No. 5 is located 660 ft. from [N] line and 1960 ft. from [E] line of sec. 10
14 14 14
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Drickey- ucan Chaves New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4415 ft. (estimated)

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total length 314' of 2 1/2" casing. 7 2 1/2" joints (304') & 10' of 2 1/2" spiral
old (7 jts) and 24' of 2 1/2" casing. (2 1/2" joint) set at 314' and cemented
with 150 sacks. Cement circulated. Plug was down at 4:30 p.m. July 3, 1954.
Cement was allowed to set 24 hours; the hole was bailed dry and no fluid
entered the 2 1/2" casing during a 5 minute period. Test was satisfactory.
filling resumed.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Cities Service Oil Company

Address Box 97

Hobbs, New Mexico

By [Signature]

Title division clerk