

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name Drickey	
Queen Sand Unit Tr 47	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
Caprock Queen	
12. County	
Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS
DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> P & A	30-005-01042
2. Name of Operator	
Weldon S. Guest & I. J. Wolfson	
3. Address of Operator	
c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, N.M. 88240	
4. Location of Well	
UNIT LETTER C 660 FEET FROM THE North LINE AND 2 1980 FEET FROM	
THE West LINE, SECTION 11 TOWNSHIP 14 S RANGE 31 E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
4393	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Subject well was re-entered to salvage 7" casing and replugged 1/8/74 as follows:

Shot off 7" casing @ 450' and pulled.
Spotted 65 sack plug 360 to 460'
Spotted 60 sack plug 225 to 325'
Spotted 10 sack plug at surface, plug failed to hold.
Checked top of plug @ 59'.
Filled hole from 59' to surface with 75 sacks cement.
Mid between all plugs
Replaced surface marker, cleaned location ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Nathan E. Clegg TITLE Agent DATE 2/4/75

APPROVED BY Nathan E. Clegg DATE 2/4/75

CONDITIONS OF APPROVAL, IF ANY: