



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____

Lease No. **LC-060821-A**

Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	I
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL			

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

June 29, 1958

Well No. **2** is located **1900** ft. from **S** line and **2310** ft. from **E** line of sec. **21**

N 1/4 of SE 1/4 Sec. 21 **14S** **12E**

(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)

CAPROCK QUEN **Chaves** **New Mexico**

(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is **4234.0** ft. **01**

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 6 3/4" hole to 2925'. Set 2917.63' of 7" 20# ST&C casing at 2924'. Cemented with 100 Sax cement. WOC 24 hrs. Tested plugs and cement with 600 psi. Plugs and cement held. Drilled out cement.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Neville G. Penrose, Inc.**

Address **Box 906**

Kunice, New Mexico

By *[Signature]*

Title **Agent**