



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **MM 06173**
Unit _____

30-005-01136

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	X
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 15, 19**55**

Well No. **1-Rhodes** is located **1780** ft. from **N** line and **330** ft. from **E** line of sec. **23**
SW/4 of NW/4 (Twp.) **14-S** (Range) **31-E** (Meridian)
Dickey Queen (Field) **Chaves** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is **4414** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Report of plugging and abandonment: Spotted 25 sacks of cement from 2150' to 2129'. Spotted 10 Sacks of cement from top of hole to 390', placed 4" x 7' joint of drill pipe as marker. 9-13-55

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **LAWLESS DRILLING COMPANY, INC.**

Address **P. O. Box 3182, Odessa, Texas**

By *[Signature]*
Title **Office Manager**