

DUPLICATE

RECEIVED

Form C-103
(Revised 3-55)

NOV 1 1956
NEW MEXICO OIL CONSERVATION COMMISSION

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

NOV 1 1956 OCT 1 AM 9:45

COMPANY Donnelly Drilling Co. Inc. Box 433 Artesia, New Mexico
(Address)

LEASE Madlin WELL NO. 1 UNIT L S 26 T 14 R 31

DATE WORK PERFORMED 10-27-56 POOL Undesig.

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☐ Plugging

☒ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Set 3126' 5 1/2" 1 1/4 new casing. Cemented with 100 sacks. Drilled through Queen sand section 3107 to 3115, but plug was not drilled.

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test

Oil Production, bbls. per day

Gas Production, Mcf per day

Water Production, bbls. per day

Gas-Oil Ratio, cu. ft. per bbl.

Gas Well Potential, Mcf per day

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

Name C. M. Ludey

Title Engineer District I

Date _____

I hereby certify that the information given above is true and complete to the best of my knowledge

Name M. Donnelly

Position President

Company Donnelly Drilling Company, Inc.

NOV 1 1956