



RECEIVED

Budget Bureau No. 42-R358.4
Approval expires 12-31-60.

(SUBMIT IN TRIPLICATE)

Land Office **Las Cruces**NOV 28 1960 No. **072006**

UNITED STATES

DEPARTMENT OF THE INTERIOR

Unit **D**

GEOLOGICAL SURVEY

ARTESIA, OFFICE

JUL 30 1958

ARTESIA, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Louis July 29, 1958

Well No. **1** is located **330** ft. from **{N}** line and **330** ft. from **{W}** line of sec. **26**

NW/4 (1/4 Sec. and Sec. No.) **T-14-S** (Twp.) **R-31E** (Range) **NMPM** (Meridian)

Caprock Queen (Field) **Chaves** (County or Subdivision) **New Mexico** (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Set 10-sack plug at 3075-3098. Perforations in 5 1/2" casing were 3085-3087. Filled hole with mud. Recovered 917' of 5 1/2" pipe. Set 15-sack plug at 917' in the stub and a 15-sack plug at bottom of surface casing at 250'. Five sacks set at surface. Put up marker. Plugged on July 27, 1958.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Lee Drilling Company**Address **1007 Philtower Bldg.****Tulsa, Oklahoma**By *[Signature]*Title **Production Superintendent**