

NUMBER OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
TRANSPORTER	OIL
	GAS
HYDRATION OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

FORM C-103
(Rev 3-55)

MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

Name of Company Continental Oil Company		Address Box 460, Hobbs, New Mexico	
Case Eastcap Queen Pool Unit	Well No. 12	Unit Letter K	Section 27
Date Work Performed 3-10-64	Pool Caprock Queen	Township 14-S	Range 31-E
		County Chaves	

THIS IS A REPORT OF: (Check appropriate block)

- ☐ Beginning Drilling Operations
 ☐ Casing Test and Cement Job
 ☒ Other (Explain):
☐ Plugging
 ☐ Remedial Work

Convert to water injection

Detailed account of work done, nature and quantity of materials used, and results obtained.

This well was converted to a water injection well for use in the Eastcap Queen Pool Unit Waterflood. 8 5/8" casing is set @ 258' and 4 1/2" casing is set at 3120'. Tested casing W/2000# for 30 min. on 3-10-64. Tested O.K.

Witnessed by J.R. Cook	Position Sr. Production Foreman	Company Continental Oil Company
----------------------------------	---	---

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

ORIGINAL WELL DATA


D F Elev.	T D	P B T D	Producing Interval	Completion Date
Tubing Diameter	Tubing Depth	Oil String Diameter	Oil String Depth	
Perforated Interval(s)				
Open Hole Interval		Producing Formation(s)		

RESULTS OF WORKOVER

Test	Date of Test	Oil Production BPD	Gas Production MCFPD	Water Production BPD	GOR Cubic feet/Bbl	Gas Well Potential MCFPD
Before Workover						
After Workover						

OIL CONSERVATION COMMISSION

I hereby certify that the information given above is true and complete to the best of my knowledge.

Approved by 	Name SIGNED: JACK MARSHALL
Title	Position District Manager
Date	Company Continental Oil Company