

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Injection		7. Unit Agreement Name Eastcap Queen Pool Unit
2. Name of Operator AGUA, INC.		8. Farm or Lease Name
3. Address of Operator Box #198, Artesia, New Mexico 88210		9. Well No. 5
4. Location of Well UNIT LETTER B , 990 FEET FROM THE North LINE AND 1651 FEET FROM THE East LINE, SECTION 27 TOWNSHIP 14 South RANGE 31 East NMPM.		10. Field and Pool, or Wildcat Caprock Queen
15. Elevation (Show whether DF, RT, GR, etc.)		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On Dec. 27, 1973, spotted 25 sacks of cement at 3031', but cement didn't stay.

On Dec. 28, spotted 25 sacks of cement at 3030', but also went away. On Jan. 2, 1974, set bridge plug in 4½" casing at 3008' and placed 5 sacks cement on top. Loaded hole with mud. Shot 4½" casing at 2215', 2000', 1500', 1250', 1000', 900' and 840'. Recovered 853' - 4½" casing. On Jan. 10, spotted 35 sacks of cement at 853', 40 sacks of cement at 240', and 10 sacks at top of hole. Placed 4" marker.

Hole was abandoned on Jan. 10, 1974.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Ralph L Gray TITLE Consulting Engineer. DATE March 27, 1974

APPROVED BY John W. Runyan TITLE Geologist DATE 1-7-1974

CONDITIONS OF APPROVAL, IF ANY: