



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office _____
Lease No. **LC-060866-1**
Unit **HOERS DISTRICT**

APR 21 PM 3 53

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....	
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....	
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....	
NOTICE OF INTENTION TO ABANDON WELL.....		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

..... **April 18**, 19 **53**

Well No. **Ballard 1** is located **560** ft. from **[N]** line and **1930** ft. from **[E]** line of sec. **28**

Caprock Queen (Field) **Chaves** (County or Subdivision) **New Mexico** (State or Territory)
(Twp.) (Range) (Meridian)

The elevation of the derrick floor above sea level is **4313** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Drilled 8 3/4" hole to 3028'. Set 3024' of 7" 80# casing with 150 sacks cement. 24 hours Tested plugs with 800# pressure. Plugs held. Tested cement with 800# pressure. Cement job held. Drilled out cement.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Haville G. Penrose, Inc.**

Address **Box 988**

Elm, New Mexico

By **Blum B. Reid**

Title **Agent**