	X	
1		
1		

(SUBMIT IN TRIPLICATE)

UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

Land Office					
Loase No. LC -060866					
Unit					

SUNDRY	NOTICES AND	REPORTS ON WEL	LS
NOTICE OF INTENTION TO DRILL NOTICE OF INTENTION TO CHANGE NOTICE OF INTENTION TO TEST WAY NOTICE OF INTENTION TO RE-DRILL NOTICE OF INTENTION TO SHOOT O NOTICE OF INTENTION TO PULL OR NOTICE OF INTENTION TO ABANDON	PLANS	SUBSEQUENT REPORT OF WATER SHUT-OFF SUBSEQUENT REPORT OF SHOOTING OR ACIDI SUBSEQUENT REPORT OF ALTERING CASING SUBSEQUENT REPORT OF RE-DRILLING OR REI SUBSEQUENT REPORT OF ABANDONMENT SUPPLEMENTARY WELL HISTORY	ZING
(INDIC	ATE ABOVE BY CHECK MARK NATU	RE OF REPORT, NOTICE, OR OTHER DATA)	
	149 31K	March 28 line and 1980ft. from $\left\{\begin{matrix} \mathbf{E} \\ \mathbf{W} \end{matrix}\right\}$ line	·
(½ Sec. and Sec. No.) Caprock Queen (Field)	(Twp.) (Range	New Mex	co
The elevation of the derrick	DETAILS		s mudding jobs, cement-
Drilled 15" hole t	o 185'. Set 1 8 5	of 10 3/4", 32.75#.	Cement
circulated. WOC 2	hrs. Tested p	lugs with 400# pressu	re.
Plugs held. Test	ed cement with 4	00 # pressure. Cement	t job
satisfactory. Dri	lling out cement	•	
_		ng by the Geological Survey before operations	-
	•	•	
Address 8ex 988			450
- Eunice,	New Mexico	By Senn	D. True
•		TitleAgent_	

U. S. GOVERNMENT PRINTING OFFICE 16-8437-5