



(SUBMIT IN TRIPLICATE)
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Budget Bureau No. 42-R358.4.
Form Approved.

Land Office LC
Lease No. 068370
Unit 0

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	Subsequent Report of Conversion to water Injection Service	X

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

October 8, 1963
South Caprock Queen Unit
Tract 7-A
Well No. 15-2 is located 990 ft. from S line and 1980 ft. from E line of sec. 33
SE 1/4, Sec. 33 14-S 31-E NMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Caprock Queen Chaves New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4442 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Pulled rods, pump and tubing.
Cleaned out to ETD of 3128'.
Ran 3072' of 2" eue, 6rr, J-55 plastic lined tubing to 3082' with ~~XXXXXX~~ tension packer on bottom. Set packer with 10,000# tension.
Placed well on injection on 10-1-63.
Current rate: 844 B/D at 980 psig.

Authority Administrative Order WFK-100.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Union Oil Company of California

Address 200 East Washington
Lovington, New Mexico

By Richard H. Butler
Richard H. Butler
Title Unit Engineer