

OIL CONSERVATION COMMISSION

SANTA FE, NEW MEXICO

Miscellaneous Reports on Wells

RECEIVED

OCT - 9 1950

COMMISSION

Submit this report in triplicate to the Oil Conservation Commission or its proper agent within ten days after the work specified is completed. It should be signed and sworn to before a notary public for reports on beginning drilling operations, results of shooting well, results of test of casing shut off, result of plugging of well, and other important operations, even though the work was witnessed by an agent of the Commission. Reports on minor operations need not be signed and sworn to before a notary public. See additional instructions in the Rules and Regulations of the Commission.

Indicate nature of report by checking below.

REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON REPAIRING WELL	
REPORT ON RESULT OF SHOOTING OR CHEMICAL TREATMENT OF WELL		REPORT ON PULLING OR OTHERWISE ALTERING CASING	
REPORT ON RESULT OF TEST OF CASING SHUT-OFF		REPORT ON DEEPENING WELL	
REPORT ON RESULT OF PLUGGING OF WELL	<input checked="" type="checkbox"/>		

October 7, 1950

Monument, New Mexico

Date

Place

OIL CONSERVATION COMMISSION,
SANTA FE, NEW MEXICO.
Gentlemen:

Following is a report on the work done and the results obtained under the heading noted above at the _____

Amarada Petroleum Corporation

State R "A"

Well No. 1 in the _____

Company or Operator

Lease

C/SW/4 SW/4

of Sec. 22

T

8-5

R

32-E

N. M. P. M.,

Wildcat

Field

Chaves

County.

The dates of this work were as follows: October 5 & 6, 1950

Notice of intention to do the work was ~~submitted~~ submitted on Form C-102 on October 4, 1950

and approval of the proposed plan was ~~obtained~~ obtained. (Cross out incorrect words.)

DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED

11621' - Total Depth - Granite Wash. Spotted 35 sacks cement at 11621', 35 sacks cement at 11018', 35 sacks cement at 4950', 35 sacks cement at 3525', recovered 178.33' of 8-5/8" casing and spotted 50 sacks cement at 200'. Plugged top of 13-3/8" surface casing with 10 sacks cement. Set a piece of 4" line pipe, as marker, in top of surface casing, extending four (4) feet above ground level. Well plugged & abandoned at 10:30 A.M., October 6, 1950.

Witnessed by E. E. Shirley Amarada Petroleum Corporation Farm Boss
Name Company Title

Subscribed and sworn before me this _____

I hereby swear or affirm that the information given above is true and correct.

9th day of October, 1950

Name E. J. Tapp

Position Assistant District Superintendent

Representing Amarada Petroleum Corporation
Company or Operator

My commission expires 10-24-53

Address Drawer B, Monument, New Mexico

Remarks:

APPROVED

Date OCT - 9 1950

Engineer District 1

Name

Title