

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYLand Office Roswell
Lease No. 1M 025819
Unit _____

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

July 8, 1964


Well No. 1 Signal Federal is located 660 ft. from N line and 660 ft. from E line of sec. 21
NE NE Sec 21 9S 31E NMPM
Wildcat Chaves New Mexico
(Field) (County or Sub-division) (State or Territory)

The elevation of the derrick floor above sea level is _____ ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

We plugged 6/2/64 as follows: pulled 1493 feet 4 1/2 inch casing and set cement plugs as follows: 25 sax 3850-3900 feet; 25 sax 3100-3200 feet; 30 sax 1475-1575 feet; 30 sax 1300-1200 feet; 300 sax at 300 feet and 15 sax at surface. Steel marker erected and pits leveled.


NMOCC - ARTESIA
NMOCC - HOSBS
BLM - SANTA FE

RECEIVED

JUL 13 1964

RECEIVED
JUL 10 1964
U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company I. W. Lovelady ROSSELL, NEW MEXICOAddress Bcx 951, Midway, TexasBy Ernest SmithTitle Agent