

FORM 7-64
(Feb. 1961)

N. M. D. C. COPY

Budget Bureau No. 42-R358.4.
Form Approved.

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office Artesia

Lease No. NM 080123

Unit West Cap UREA Sand Unit

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL.....	SUBSEQUENT REPORT OF WATER SHUT-OFF.....
NOTICE OF INTENTION TO CHANGE PLANS.....	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING.....
NOTICE OF INTENTION TO TEST WATER SHUT-OFF.....	SUBSEQUENT REPORT OF ALTERING CASING.....
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL.....	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR.....
NOTICE OF INTENTION TO SHOOT OR ACIDIZE.....	SUBSEQUENT REPORT OF ABANDONMENT.....
NOTICE OF INTENTION TO PULL OR ALTER CASING.....	SUPPLEMENTARY WELL HISTORY.....
NOTICE OF INTENTION TO ABANDON WELL.....	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 21, 1964

Well No. 944 is located 2150 ft. from N line and 974 ft. from E line of sec. 21
NE/4 Section 21 T14S R31E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Caprock Queen Chaves New Mexico
(Field) (County or Subdivision) (State or Territory)

RECEIVED
FEB 25 1964
D. C. C.
ARTESIA, OFFICE

The elevation of the derrick floor above sea level is 4307 ft. GL

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Halliburton cemented 4-1/2" (9.5# J-55) casing at 3049' with 300 sacks regular cement. Pumped plug to 3039'. WOC 21 hours. Tested casing with 1500# for 30 minutes, no pressure loss. Temperature survey top of cement at 2000'.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Phillips Petroleum Company

Company _____

Address Box 2130 - Hobbs, N.M.

By W. H. Robertson
Office Manager

Title _____