

Land Office Artesia

(SUBMIT IN TRIPLICATE)

HOBBBS OFFICE

Case No. NH 080123UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYUnit West Cap Queen Sand Unit

SUNDRY NOTICES AND REPORTS ON WELLS

| | |
|---|---|
| NOTICE OF INTENTION TO DRILL..... | SUBSEQUENT REPORT OF WATER SHUT-OFF..... |
| NOTICE OF INTENTION TO CHANGE PLANS..... | SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING..... |
| NOTICE OF INTENTION TO TEST WATER SHUT-OFF..... | SUBSEQUENT REPORT OF ALTERING CASING..... |
| NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL..... | SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR..... |
| NOTICE OF INTENTION TO SHOOT OR ACIDIZE..... | SUBSEQUENT REPORT OF ABANDONMENT..... |
| NOTICE OF INTENTION TO PULL OR ALTER CASING..... | SUPPLEMENTARY WELL HISTORY..... |
| NOTICE OF INTENTION TO ABANDON WELL..... | |

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

February 21, 1964

Well No. 9W4 is located 2150 ft. from [N] line and 974 ft. from [E] line of sec. 21
NE/4 Section 21 T14S R31E
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
Caprock Queen Chaves New Mexico
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 4307 ft. GL

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Cactus Drilling Company spudded at 9:45 PM 10-28-63.

Halliburton cemented 8-5/8" (24# J-55) casing at 122' with 125 sacks regular cement (2% CaCl). Plumped plug to 100'. Cement circulated. WOC 19 hours. Tested casing with 800# for 30 minutes, no pressure loss.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Phillips Petroleum Company - operatorAddress Box 2130 - Hobbs, New MexicoBy W. C. CrostonTitle Office Manager