

HOBBS OFFICE O. C. C.
OCT 30 3 28 PM '63

UNION OIL COMPANY OF CALIFORNIA

SOUTH CAPROCK QUEEN UNIT, TRACT 29 - WELL NO. 7-20


In accordance with Rule 111, results of deviation surveys made on the Union Oil Company of California's South Caprock Queen Unit, Tract 29, Well No. 7-20 are furnished as follows:

<u>ANGLE</u>	<u>DEPTH</u>
3/4	360
1/2	692
1/2	1192
1/2	1690
1/2	2190
1/4	2445
1	2948
1	3225

I hereby certify that all deviation tests set forth above are true and correct to the best of my knowledge.


for Union Oil Company of California

Subscribed and sworn to before me, a Notary Public in and for
Midland County, State of Texas, this 29th day of October, 1963.


Helen M. Nichols

CORE NO. 1: 3160 - 3184': Recovered 24', being 1 1/2' dolomite, 2' hard sand, 13' black sand, 4 1/2' red and grey sand with no show, 1' of red sand with no show, and 2' of dolomite.