

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIP
(Other instruction
verse side)

TE
FC

Form approved.
Budget Bureau No. 42-R1424.

NMOCC - ARTESIA
NMOCC - HOBBS
BLM - SANTA FE

SUNDY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different interval.
Use "APPLICATION FOR PERMIT—" for such proposals.)

6. LEASE DESIGNATION AND SERIAL NO.

NM-0403706

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1 23 PM '66

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

ABKO FEDERAL

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

CATO SAN ANDRES (Ext)

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

10-8-30 N M PM

12. COUNTY OR PARISH

CHAVES

13. STATE

N.M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

Box 68 Hobbs N.M.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1980' FNL & 1980' FEL, Sec 10 (UNIT G, SW 1/4 NE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4118' R.D.B.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

TD-3548, On 7-28-66, 4 1/2" OD G.S. J-55 Casing was set at 3548' w/ 500 04 12% Bll + 300 04. Next. After NOC 24 hours, tested casing w/ 1800 psi for 30 minutes. Test O.K. PBD-3510. Perforated intervals 3300-07, 17-25, 27-36, 72-80 85-89, 95-02, 3408-14 w/ 2SPF. Acidized w/ 2000 gal. Evaluated.

On PT, 5 hrs, flw. 73 BO x 2 BLW. 18 1/2" Ch. HOR 840, Cgr. 25.5"

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Engineer

DATE

8-1-66

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

4 USGS-ROSWELL
1-NSW
1-SUSP
1-RRY



*See Instructions on Reverse Side

RECEIVED

AUG 3 1966

U. S. GEOLOGICAL SURVEY
ROSWELL NEW MEXICO