

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/> 5. State Oil & Gas Lease No.
1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name	
2. Name of Operator Atlantic Richfield Company	8. Farm or Lease Name State "BF"	
3. Address of Operator P. O. Box 1978, Roswell, New Mexico	9. Well No. 6	
4. Location of Well UNIT LETTER G 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 3 TOWNSHIP 8-S RANGE 33-E NMPM.	10. Field and Pool, or Wildcat Chaveroo-San Andres	
15. Elevation (Show whether DF, RT, GR, etc.) 4397' DF	12. County Chaves	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Drilled a 7-7/8" hole to 4456' T.D. Ran electric logs. Ran 137 jts 4-1/2" OD 8R 10.5# J-55 ST&C casing w/float shoe and float collar = 4444.40'. Set at 4455' RKB. Cemented w/300 sx 1:1 Incor-Diamix. Plug down at 2:36 AM 7/28/66. Top of cement at 3211' by temperature survey. After 58 hrs WOC tested 4-1/2" casing to 1500# for 30 min. Held OK. Perforated San Andres w/one 3/8" jet shot at 4208, 4245, 4267, 4308, 4314, 4323, 4339, 4350 and 4356' (9 holes). Treated w/3000 gallons 15% HCl, 5000 gallons lease crude + 1/20#/gal Adomite, 20,000 gallons lease crude + 1/20#/gal Adomite & 30,000# of 20/40 sand. Landed 2" tubing at 4217.75'. Swabbed and flowed all of load oil. On 16 hour potential test, flowed 101 BNO & 9 BW.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed
SIGNED O. D. Bretches TITLE Dist. Drlg. Supervisor DATE 8-4-66

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: