

UNITED STATES
DEPARTMENT OF THE INTERIOR

SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved,
Budget Bureau No. 42-R1424,
5. LEASE DESIGNATION AND SERIAL NO.

NM000 - ARTESIA
NM000 - HOBBS
BLM - SANTA FE

GEOLOGICAL SURVEY
HOBBS OFFICE D. C. C.

SUMMARY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill into or through a different reservoir.
Use "APPLICATION FOR PERMIT TO DRILL" (Form 9-132)

NM-0403706

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER

2. NAME OF OPERATOR

Pan American Petroleum Corp.

3. ADDRESS OF OPERATOR

Box 68 Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL X 660' FWL, Sec. 1 (Unit M, SW/4 SW/4)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

ABKO Federal "B"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

CATO San Andres

11. SEC., T., R., M., OR B.L.K. AND
SURVEY OR AREA

1-8-30 NMPM

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

12. COUNTY OR PARISH

Chaves

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Chico Drilg. Co., spudded 12 1/4" hole, 3:00 P.M. 11-6-66.
Set 8 5/8" O.D. 24" J-55 Casing at 457' with 300 sx. neat
Cement circulated. After 74 OC 18 hours tested
casing w/ 1000 psi for 30 minutes. Test OK.

Reduced hole to 7 7/8" @ 457' and resumed
drilling operations.

RECEIVED
NOV 14 1966
U. S. GEOLOGICAL SURVEY
ROSWELL, N.M.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Area Supt

DATE

11-8-66

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

0+4- USGS-14
1- NSW
1- SUSP
1- W-7



*See Instructions on Reverse Side