

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

NM0000 - ARIZONA

NM0000 - HOBBS

BLM - SANTA FE

SUNDAY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

HOBBS OFFICE O. C. C.

JAN 13 11 41 AM '67

5. LEASE DESIGNATION AND SERIAL NO.

NM-0254700

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

FISCHER Federal

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

CATO San Anares

11. SEC. T., R., M., OR BEK. AND
SURVEY OR AREA

12-8-30 NMPM

12. COUNTY OR PARISH 13. STATE

CHAVER N.M.

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ Drilling

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FWL x 660' FWL Sec. 12 (Unit E, SW 1/4 NW 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DT, ST, CR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLET

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones parti-
nent to this work.)*

Cactus Drilling Co., spudded 11" hole 7:PM 1-11-67 and set
8 7/8" OD 24" J-55 casing @ 460' w/ 300 CY Cement.
Circulated. After WOC 18 hours, tested casing
w/ 1000 psi for 30 minutes. Test O.K.

Reduced hole to 7 7/8" @ 460' and resumed drilling.

RECEIVED

JAN 13 1967



18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE AREA SUPERINTENDENT

DATE 1-13-67

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

DATE

DATE

014- USGS- ROSWELL
1- NSW
1- SUSP
1- RRY

*See Instructions on Reverse Side