

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

NM0000 - ARIZONA

NM0000 - NEW MEXICO

BLM - SANTA FE

SUNDARY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

JAN 26 11 23 AM '67

5. LEASE DESIGNATION AND SERIAL NO.

NM 0444628

6. IF INDIAN ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CATO "C" Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

CATO San Andres

11. SEC. T., R., M., OR BLK. AND
SURVEY OR AREA

14-8-30 NMPM

12. COUNTY OR PARISH 13. STATE

Chaves N.M.

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ *Drilling*

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FSL * 1980' FEL Sec 14 (Unit J, NW 1/4 SE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, OR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Cactus Drilling Co. squadded 11" hole 11:15 PM, 1-20-67.
At 5:20 PM, 8 5/8" OD 24 #1-55 casing was set @ 470'
w/ 300 #4. Cement circulated. After 1400 18 hours
tested casing w/ 1000 psi for 30 minutes.
Test O.K.

Reduced hole to 7 7/8" @ 470 and resumed drilling.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE

1-24-67

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

01-4 USGS-ROSWELL
1-NSW
1-SUSP
1-RRY

*See Instructions on Reverse Side

RECEIVED
JAN 25 1967U. S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO