

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPlicate
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

NM000 - ARTICIA
NM000 - HOBBS
BLM - SANTA FE

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.

5. LEASE DESIGNATION AND SERIAL NO.
NM-0155494

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

FEB 9 11 17 AM '67

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ *Drilling*

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)

1980' FNL x 1980' FEL, Sec. 9 (Unit G, SW 1/4 NE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether BP, ST, GR, etc.)

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CROSBY "B" Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

CATO San Andres

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

9-8-30 N MPM

12. COUNTY OR PARISH

Charles

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETS

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Cactus Drilg Co., squadded 11" hole, 11:00AM, 2-4-67.
8 5/8" OD 24" J-55 casing was set @ 460' w/ 300 sy.
Cement circulated. After 1400 18 hours, tested casing w/1000 psi for 30 minutes. Test O.K.
Reduced hole to 7 7/8" @ 460' and resumed drilling

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE AREA SUPERINTENDENT

DATE 2-7-67

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

014-USGS-RDS
1-NSW
1-SUSP
1-RRY

*See Instructions on Reverse Side

FEB 8 1967

SUTHERLAND