

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPlicate*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

NM988 - ARIZONA
NM988 - HOBBS
BLM - SANTA FE

SUNDARY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.

6. LEASE DESIGNATION AND SERIAL NO.

NM-0142233

6. MINER, ALLOTTEE OR TRIBE NAME

AM '67

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CROSBY "A" Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

CATO San Anas

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

8-8-30 N M P M

12. COUNTY OR PARISH, STATE

Charles N. M.

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSE X 660' FEL, Sec. 8 (Unit P, SE 1/4 SE 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☒

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) *Spudding* ☒

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Chico Drilg Co. spudded 12 1/4" hole 11:AM 2-10-67.
8 5/8" OD 24" J-55 Casing was set @ 470' w/ 300 sq.
Cement circulated. After MOC 18 hours, tested
casing w/ 1000# psi for 30 minutes. Test
O.K.

Reduced hole to 7 7/8" @ 470' and resumed
drilling.

RECEIVED

FEB 15 1967

U.S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE AREA SUPERINTENDENT

DATE

4-13-67

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

0+ 4-USGS-Ras
1-N.S.W.
1-SUSP
1-RRV

*See Instructions on Reverse Side

