

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1434.NMOCC - ~~HOBBES~~
NMOCC - HOBBES
BLM - SANTA FE

SUMMARY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.

MAR 9 11 30 AM '67

5. LEASE DESIGNATION AND SERIAL NO.

NM-0177517

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

CATO B Federal

9. WELL NO.

R

10. FIELD AND POOL, OR WILDCAT

CATO San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

14-B-30

12. COUNTY OR PARISH

Chaves

13. STATE

N.M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PAN AMERICAN PETROLEUM CORPORATION

3. ADDRESS OF OPERATOR

BOX 68, HOBBS, N. M. 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' FSL x 1980' FWL, Sec 14 (UNIT N, SE 1/4 SW 1/4)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, WT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

On 2-28-67, 4 1/2" OD 9.5" J-55 Casing was set @ 3660' (TD)
w/ 500 cu 12% gel + 300 cu neat. Tested casing w/
2200 psi for 30 minutes. Test O.K. Perforated
interval 3572-3619 w/ 2 1/2" SP. Acidized w/ 3000 gal 28%
Evaluated.

PT. in 12 hours, flow 114 BO + 7 BLW thru 18 1/4" choke.
TPF-200, CPF-300. BOB 530, 60 MCFG

TD 3660'
PAD-3635'
TPV 3572, San An.

Comp. 3-3-67

R E O

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

AREA SUPERINTENDENT

DATE 3-7-67

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

0-4- USGS. ROSAELL
1- NSW
1- SUP
1- RRY

*See Instructions on Reverse Side

ACCEPTED FOR RECORD

District Engineer