

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N. M. OIL CONS. COMMISSION
P. O. BOX 1980
HOBBS, NEW MEXICO 88241

Budget Bureau No. 1104-0107
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.
NM-0403706

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
Cato Storage System III

8. FARM OR LEASE NAME

See Item 17

9. WELL NO.

See Item 17

10. FIELD AND POOL, OR WILDCAT

Cato San Andres

11. SEC., T., R., M., OR B.E. AND
SURVEY OR AREA

Township 8S, Range 30 E

12. COUNTY OR PARISH; 13. STATE

Chaves

NM

1. ☒ WELL ☐ OTHER

2. NAME OF OPERATOR

APOLLO ENERGY, INC.

3. ADDRESS OF OPERATOR

P.O. Box 5315, Hobbs NM 88241

4. LOCATION OF WELL (Report location clearly and in accordance with New Mexico requirements.
See also space 17 below.)
At surface

Storage System III located SW/4 NE/4 Section 10, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

PULL OR ALTER CASING ☐

FRACTURE TREAT ☐

MULTIPLE COMPLETE ☐

SHOOT OR ACIDIZE ☐

ABANDON* ☐

REPAIR WELL ☐

CHANGE PLANS ☐

(Other) Commingled Cato SSIII Tests ☒

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

REPAIRING WELL ☐

FRACTURE TREATMENT ☐

ALTERING CASING ☐

SHOOTING OR ACIDIZING ☐

ABANDONMENT* ☐

(Other) ☐

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to the work.)

APOLLO ENERGY requests approval to continue current practice of testing wells by a portable well tester rather than using mostly "out of service" separator meters at each battery in the Cato San Andres Field.

Almost all wells in the Cato Field are stripper averaging 2-3 BOPD and some water. It has been APOLLO'S experience over the last 4½ years in this field, the well tests are more dependable & cost effective under the present system than the previous ones which I believe were not used in years (I suspect the tests were "boiler house").

CATO STORAGE SYSTEM III:

NM-0403706 Abko Federal - NE/4 Section 10, Wells #1, #2, #3, & #4

NM-0142233 Crosby A Federal - E/2 SE/4 Section 8, Wells # 1 & #2

NM-0155494 Crosby B Federal - W/2 NE/4 Section 9, Wells #1 & #2

NM-0354427A Grimm Federal - W/2 SE/4 Section 9, Wells #1 & #2

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE PRESIDENT

DATE 11-5-86

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
DATE
PETER W. CHESTER

DEC 3 1986

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side